Figure B: 21. White Slums, at Broughton and Houston Streets, AASU Lane Library, Savannah, Georgia, (*Living in Savannah*, Book 1, Page 41, Image no. 03, http://www.library.armstrong.edu/lis1/lis1-01.html).

Figure B: 22. White Slums at Tattnall and Berrien Streets, AASU Lane Library, Savannah, Georgia, (*Living in Savannah*, Book 1, Page 41, Image no. 06, http://www.library.armstrong.edu/lis1/lis1-01.html).

Figure B: 23. White Home in Old Fort Section, AASU Lane Library, Savannah, Georgia, (*Living in Savannah*, Book 1, Page 43, Image no. 01, http://www.library.armstrong.edu/lis1/lis1-01.html).

Figure B: 24. White Home in Old Fort Section, AASU Lane Library, Savannah, Georgia, *(Living in Savannah*, Book 1, Page 43, Image no. 04, http://www.library.armstrong.edu/lis1/lis1-01.html).

Appendix C: Isaiah Davenport House Exterior



Figure C: 1. Floor plans of basement and first floor of the Isaiah Davenport House, 1936. Historic American Building Survey Drawings, Washington, DC, (Isaiah Davenport House, http://lcweb2.loc.gov/ammem/collections/habs_haer/).



Figure C: 2. Floor plans of the attic and second floor of the Isaiah Davenport House, 1936. Historic American Building Survey Drawings, Washington, DC, (Isaiah Davenport House, http://lcweb2.loc.gov/ammem/collections/habs_haer/).



Figure C: 3. Exterior views of the north and west facades of the Isaiah Davenport House, 1936. Historic American Building Survey Drawings, Washington, DC, (Isaiah Davenport House, http://lcweb2.loc.gov/ammem/collections/habs_haer/).



Figure C: 4. Exterior views of the south and east facades of the Isaiah Davenport House, 1936. Historic American Building Survey Drawings, Washington, DC, (Isaiah Davenport House, http://lcweb2.loc.gov/ammem/collections/habs_haer/).

OLD HOUSE COMING BACK INTO ITS OWN—A view of the interior of the famous old Georgian residence which Historic Savannah saved from destruction. Seen on the landing of the handsome spiral staircase is L. D. Chestnut, with (center) Eugene Shuman, assistant electrician and L. D. Williams, carpenter. Under the turn of the stairway can be seen a portion of the fluted cornice which sweeps upward to continue along the walls of the hallway. (Morning News Photo by Jim Bisson.)

Figure C: 5. Photograph of the interior of the parlor level's hallway of the Isaiah Davenport House. Live Oak Libraries-Main Branch-Bull Street, Georgia Room, Vertical File: "Davenport House."

Figure C: 6. Photograph of the exterior of the Isaiah Davenport House before construction of store front door in 1940s. Isaiah Davenport House Museum, Savannah, Georgia, (Reference Files).

Figure C: 7. From this photograph of the Isaiah Davenport House exterior, broken window panes can be seen. Isaiah Davenport House Museum, Savannah, Georgia, (Reference Files).

Figure C: 8. The photograph of the exterior of the Isaiah Davenport House shows broken window panes, the remaining awning support, and the store front door. Isaiah Davenport House Museum, Savannah, Georgia, (Reference Files).



Figure C: 9. Exterior photograph of the south façade of the Isaiah Davenport House. Isaiah Davenport House Museum, Savannah, Georgia, (2002 Historic Structures Report).

Figure C: 10. Undated exterior view of the southeast façade of the Isaiah Davenport House. The Chatham Apartments are also visible. Isaiah Davenport House Museum, Savannah, Georgia, (2002 Historic Structures Report).

Figure C: 11. Exterior view of the Isaiah Davenport House south façade. The door on the southwest is visible Isaiah Davenport House Museum, Savannah, Georgia, (2002 Historic Structures Report).



Figure C: 12. Exterior photograph of the Isaiah Davenport House in 1948. Live Oak Libraries-Main Branch– Bull Street, Georgia Room, Vertical File: "Davenport House."

Figure C: 13. The Isaiah Davenport House as a tenement in the 1940s. Isaiah Davenport House Museum, Savannah, Georgia, (Reference Files).



Figure C: 14. An undated exterior view of the south façade of the Isaiah Davenport House. Isaiah Davenport House Museum, Savannah, Georgia, (2002 Historic Structures Report).

Figure C: 15. Undated exterior view of the Isaiah Davenport House. Isaiah Davenport House Museum, Savannah, Georgia, (2002 Historic Structures Report).

Figure C: 16. Undated exterior view of the Isaiah Davenport House. Isaiah Davenport House Museum, Savannah, Georgia, (2002 Historic Structures Report).

Figure C: 17. Photograph of the building's exterior after HSF bought and restored the property. Historic American Building Survey Drawings, Washington, DC, (Isaiah Davenport House, http://lcweb2.loc.gov/ammem/collections/habs_haer/).

Figure C: 18. An undated photograph of the northeast corner of the Isaiah Davenport House. Historic American Building Survey Drawings, Washington, DC, (Isaiah Davenport House, http://lcweb2.loc.gov/ammem/collections/habs_haer/).



Figure C: 19. Undated photograph of the northeast elevation of the Isaiah Davenport House. The Chatham Apartments are also visible. Isaiah Davenport House Museum, Savannah, Georgia, (2002 Historic Structures Report).

Appendix D: Isaiah Davenport House Interior



Figure D: 1. Interior photograph of the Isaiah Davenport House attic in the early twentieth century. Georgia Historical Society, Savannah, Georgia, Vertical File: "Davenport House," *Old Home Now Newest Museum.*

Figure D: 2. A photograph of the central hallway of the parlor floor of the Isaiah Davenport House, 1934. Historic American Building Survey, Washington, DC, (Isaiah Davenport House, http://lcweb2.loc.gov/ammem/collections/habs_haer/).

Figure D: 3. Interior photograph of parlor floor's central hallway. Most likely a HABS photograph taken from unknown book. Isaiah Davenport House Museum, Savannah, Georgia (Reference Files).

Figure D: 4. Undated interior view of the central hallway of the Isaiah Davenport House. Isaiah Davenport House Museum, Savannah, Georgia, (2002 Historic Structures Report).

Figure D: 5. An undated interior view of the central hallway of the Isaiah Davenport House. The covered window on the stairs is visible. Isaiah Davenport House Museum, Savannah, Georgia, (2002 Historic Structures Report).

Figure D: 6. Undated interior photograph of the parlor. Isaiah Davenport House Museum, Savannah, Georgia, (2002 Historic Structures Report).

Figure D: 7. Interior photograph of the parlor, 1934. Historic American Building Survey, Washington, DC, (Isaiah Davenport House, http://lcweb2.loc.gov/ammem/collections/habs_haer/).

Figure D: 8. Undated interior view of the parlor. Isaiah Davenport House Museum, Savannah, Georgia, (2002 Historic Structures Report).



Figure D: 9. Undated interior photograph of Mr. Davenport's office. Isaiah Davenport House Museum, Savannah, Georgia, (2002 Historic Structures Report).

Figure D: 10. Undated interior photograph of Mr. Davenport's office. Isaiah Davenport House Museum, Savannah, Georgia, (2002 Historic Structures Report).

Appendix E: Savannah Maps



Figure E: 1. Map of the city of Savannah, Georgia. 1884 Hogg Map. Hargrett Library Rare Map Collection. (Savannah & the Coast, http://www.libs.uga.edu/darchive/hargrett/maps/coast.html).



Figure E: 2. Context of Isaiah Davenport House. 1884 Sanborn Fire Insurance Map of Savannah, Georgia. Index Map.
(http://dlg.galileo.usg.edu/sanborn/CityCounty/Savannah.html).



Figure E: 3. Close-up view of the Isaiah Davenport House. Sanborn Fire Insurance Map 1884. Sheet 10. http://dlg.galileo.usg.edu/sanborn/CityCounty/Savannah.html



Figure E: 4. Context of Isaiah Davenport House. 1888 Sanborn Fire Insurance Map of Savannah, Georgia. Sheet 9.
http://dlg.galileo.usg.edu/sanborn/CityCounty/Savannah.html



Figure E: 5. Close-up view of the Isaiah Davenport House. 1888 Sanborn Fire Insurance Map of Savannah, Georgia. Sheet 9.
http://dlg.galileo.usg.edu/sanborn/CityCounty/Savannah.html

Figure E: 6. Context of Isaiah Davenport House. 1898 Sanborn Fire Insurance Map of Savannah, Georgia. Sheet 19.
http://dlg.galileo.usg.edu/sanborn/CityCounty/Savannah.html

Figure E: 7. Close-up view of the Isaiah Davenport House. 1898 Sanborn Fire Insurance Map of Savannah, Georgia. Sheet 19.
http://dlg.galileo.usg.edu/sanborn/CityCounty/Savannah.html



Figure E: 8. Close-up of Columbia Square. The Chatham Apartments can be seen north of the Isaiah Davenport House. 1916 Vol. Sanborn Fire Insurance Map of Savannah, Georgia. Sheet16. http://dlg.galileo.usg.edu/sanborn/CityCounty/Savannah.html



Figure E: 9. 222 East State Street. 404 East State Street no longer exists. 1916 Vol. 1 Sanborn Fire Insurance Map of Savannah, Georgia. Sheet 16. (http://dlg.galileo.usg.edu/sanborn/CityCounty/Savannah.html).

Appendix F: Furnishing Visuals



Figure F: 1.The existing garden floor plan of the Isaiah Davenport House. Isaiah Davenport House Museum, Savannah, Georgia, (2002 Historic Structures Report).



Figure F: 2. The proposed demolition of non-historic partition walls. Courtesy of the author.



Figure F: 3. The proposed reconstruction of historic partition walls. Courtesy of the author.



Figure F: 4. Proposed furnishing layout of the garden floor plan of the Isaiah Davenport House. Courtesy of the author.



Figure F: 5. A view of the furnished garden level room. Courtesy of the author.



Figure F: 6. A perspective on the proposed furnishing of the southeast room of the garden floor of the Isaiah Davenport House. Drawn by Chris Folk and the author.



Figure F: 7. A perspective on the proposed furnishing of the southeast room of the garden floor of the Isaiah Davenport House. Drawn by Chris Folk and the author.



Figure F: 8. The existing attic floor plan of the Isaiah Davenport House. Isaiah Davenport House Museum, Savannah, Georgia, (2002 Historic Structures Report).



Figure F: 9. Proposed furnishing layout of the attic floor plan of the Isaiah Davenport House. Courtesy of the author.



Figure F: 10. View of the furnished attic room. Courtesy of the author.



Figure F: 11. A perspective on the proposed furnishing of the southwest room of the attic floor of the Isaiah Davenport House. Drawn by Chris Folk and the author.



Figure F: 12. A perspective on the proposed furnishing of the southwest room of the attic floor of the Isaiah Davenport House. Drawn by Chris Folk and the author.

Figure F: 13. The northwest office of the garden level.

Figure F: 14. The west hallway where the offices are located on the garden level.

Figure F: 15. Garden level hallway at base of stairs.

Figure F: 16. North hall of the garden level.

Figure F: 17. Center hall of the garden floor looking into the southeast room.

Figure F: 18. The museum shop or the southeast room where Mrs. Carter lived.

Figure F: 19. In the southeast room of the garden level looking north.



Figure F: 20. The north rear entryway on the garden level.

Figure F: 21. The wall along the stairs.

Figure F: 22. Southwest corner of the southwest attic room to be interpreted, presently housing the museum's collections.



Figure F: 23. The west wall of the southwest attic room.

Figure F: 24. The northeast corner of the attic room to be interpreted.

Figure F: 25. The north wall looking into the northwest room.

Figure F: 26. Looking east toward the southwest attic room entrance.

Figure F: 27. The northwest corner of the southwest attic room.

Figure F: 28. The southeast corner of the southwest attic room.

Figure F: 29. Close-up of evidence that the attic had a coal stove.



Figure F: 30. The south wall of the southwest attic room.

Figure F: 31. Patterned wallpaper.

Figure F: 32. Sheet metal used to cover up drafts.

Figure F: 33. Remains of wallpaper.

Figure F: 34. Wallpaper and border paper remains.

Figure F: 35. Wallpaper and border paper.

Figure F: 36. The attic door leading to the attic hallway.

Figure F: 37. The attic door looking from the hallway.

Figure F: 38. Close-up of the present locking system on the attic floor.

Figure F: 39. Western Electric Dial Telephones were sold from 1919-1930. A telephone can be seen in Mr. Davenport's office. AT&T Company, (History of AT&T, http://www.corp.att.com/history/milestone_1919.html).

Figure F: 40. End table with book trough. Harriet and Robert W, Swedberg, *Furniture of the Depression Era: Furniture & Accessories of the 1920s, 1930s, & 1940s,* Collector Books, 1994, 44.

No. 48—Buffet. Top, 24x72 inches. Height, 40½ inches. List price, $195.00.



Buffet. Top, 21x66 inches.

Figures F: 41-42. Buffet tables from the Rockford Chair and Furniture Company with dining room set. Don Fredgant, *American Manufactured Furniture: A Complete Guide to Furniture Produced in the 1920s,* Schiffer Publishing, 1996, 308, 323.

No. 185-54SAT—
Black.

Figure F: 43. A similar high chair from the Phoenix Chair Company. Don Fredgant, *American Manufactured Furniture: A Complete Guide to Furniture Produced in the 1920s,* Schiffer Publishing, 1996, 235.





Figures F: 44-45. Drop-leaf dining tables. Celia Jackson Otto, *American Furniture of the Nineteenth Century, Viking Press, 1965, Figures 71, 73.*



Figure F: 46. Oval gilt mirror as seen in foyer photograph. Thomas H. Ormsbee, *Field Guide to American Victorian Furniture*, Bonanza Books, 1952, 377, Figure 243.

Figure F: 47. Machine turned dining and side chairs. Thomas H. Ormsbee, *Field Guide to American Victorian Furniture*, Bonanza Books, 1952, 74, Figure 27.



Figure F: 48. White wicker child stroller by the Walter Heywood Chair Company. Kathryn McNerney, *Victorian Furniture: Our American Heritage, Book II,* Collector Books, 1997, 219.

Figure F: 49. An upright piano which may have been in the parlor room. Kathryn McNerney, *Victorian Furniture: Our American Heritage, Book II,* Collector Books, 1997, 87.



Figure F: 50. Brass iron bedsteads. The Sears and Roebuck Co. sold similar besteads for $8.50 in 1897. Kathryn McNerney, *Victorian Furniture: Our American Heritage, Book II*, Collector Books, 1997, *23.*

Figure F: 51. A copy of True Story magazine that can be seen in a period photograph of the Davenport office. Courtesy of the author.

Figure F: 52. A coal stove in an exhibit at the Lower East Side Tenement Museum. Raymond Bial, *Tenement: Immigrant Life on the Lower East Side.*

Figure F: 53. Chest of drawers. Period photograph of the Davenport office.



Figure F: 54-55. Stainless steel barrier systems from Absolute Products. The 1000mm is recommended. *Absolute Products* catalog.